

## Hotel air gets greener with a new chiller system

## **Loss details**

Nature of business Luxury Hotel

**Type of equipment** Air conditioning compressor

Age of equipment 20 years old During a routine maintenance inspection it was discovered that a contactor servicing one of the hotel's air conditioning compressors had failed, causing the compressor to run continuously. The specific cause of the failed contactor remains unknown.

The contactor was replaced and the system was restarted and commissioned. Later the compressor was found to be operating noisily and tripped the fuses on two electrical phases due to high current draw on start up. The technician reported that the compressor rotor and bearings had mechanically seized, likely due to operating non-stop as a result of the original contactor failure. The cost to replace the compressor was approximately \$33,000, but due to its age and the opportunity to achieve significant savings from improved energy efficiency, the Insured instead elected to replace the entire chiller system.

Under Vero's Additional equipment upgrades and green costs coverage, the Insured was able to claim an additional \$16,500 toward the cost of the new chiller system.

## **Final loss**

Settlement Amount: \$49,500

## How can I find out more?

Contact your broker or visit vero.com.au



The insurer is AAI Limited ABN 48 005 297 807 trading as Vero Insurance. Refer to the Policy for terms, conditions and exclusions. This Loss Bulletin relates to coverage available under Vero's Equipment Breakdown Insurance Policy. Read the Product Disclosure Statement before buying this insurance. Go to vero.com.au for a copy. This advice has been prepared without taking into account your particular objectives, financial situations or needs, so you should consider whether it is appropriate for you before acting on it. V11149 24/09/21 A