

Loss Bulletin

Vero Engineering Insurance

Diesel generator

Loss details

Nature of business

Glass Kitchen
Backsplash
Manufacturer

Type of equipment

800kVA Diesel
Generator

Age of equipment

4 years old

An examination of the Generator by a Technician concluded that there was no water in the cooling system, the engine sump was full of oil and water and that motor oil was leaking from every access and exit points of the engine.

The final cause could not be established, but it was narrowed down to either overheating following coolant pipe failure, loss of oil following engine block failure, or due to a fractured jacket of the Engine block.

Due to the extent of the damage and anticipated problems in sourcing replacement parts, it was decided that the best option would be to source a complete Generator of similar capacity for the Insured. In the interim, a rental generator was sourced until the suitable permanent replacement was found.

Final loss

A new replacement Diesel Generator was purchased and installed for \$221,365

Cost of hiring a temporary Generator amounted to \$93,531

Final loss settlement amounted to \$314,896



How can I find out more?

To find out more about Vero Engineering Insurance contact your broker or visit the Vero website www.vero.com.au.