Loss Bulletin

Vero Equipment Breakdown Insurance

Rag stuffs up laminating machine

Loss details

Nature of business Cabinetmaker

Type of equipment Laminating machine

Age of equipment 14 years old

Prior to relocating their veneer hot press within their shop, the Insured engaged a fluid power engineering firm to service the hydraulic system.

Once back in operation after the service, a variety of problems began to occur, from valves not functioning properly to the press not raising. The engineers discovered various components of the press such as filters, valves and oil lines were blocked with a fibrous material.

The press had been purchased 2nd hand about 7 years earlier from an overseas company. Further investigations established that when the press had been dismantled for shipping to the insured, one of the rags which had been inserted to soak up excess oil after draining the tank had become wedged behind a baffle. Because it was unseen, it was not removed and had remained in the tank in the intervening 7 years. The rag became dislodged during the hydraulic service and once the machine had been returned to service, the operation of the press resulted in the rag disintegrating and fibres circulating within the oil.

The repairs took 3 weeks but the Insured was able to avoid canceling any orders and completed all required work through the use of overtime, which was indemnified under their business interruption coverage.

Final loss

\$71,580

How can I find out more?

Contact your broker or visit vero.com.au



The insurer is AAI Limited ABN 48 005 297 807 trading as Vero Insurance. Refer to the Policy for terms, conditions and exclusions. This Loss Bulletin relates to coverage available under Vero's Equipment Breakdown Insurance Policy. Read the Product Disclosure Statement before buying this insurance. Go to vero.com.au for a copy. This advice has been prepared without taking into account your particular objectives, financial situations or needs, so you should consider whether it is appropriate for you before acting on it. V11185 22/02/22 A