

Loss Bulletin



Vero Equipment Breakdown Insurance

Court is not in session

Loss details

Nature of business

Tennis Club

Type of equipment

Tennis Court Lighting

Age of equipment

15 years

When maintenance staff discovered that one of the court lighting circuits had failed to operate, they inspected the lights themselves and saw that the bulbs on all the light fittings on that circuit had blown and that the fittings were discolored.

The club's lighting repair contractor determined that the entire lighting circuit had been affected and that all fittings would need to be replaced with new fittings because the component parts (other than the bulbs themselves) were obsolete.

The damage was caused by a voltage fluctuation of unknown origin, and there was no evidence of lightning in the vicinity at the time of the breakdown. Unfortunately, the equipment was not protected against such a power spike.



Final loss

Settlement amount \$41,448.00

How can I find out more?

Contact your broker or
visit vero.com.au