

Loss Bulletin

Vero Engineering Insurance

Problems Stack up for Strata

Loss details

Nature of business

Residential Strata

Type of equipment

Car Stacker

Age of equipment

5 years old

During the operation of the 24 car stacker, a variance developed between the speed of the cart and the speed of the cable drum retraction/rewind unit which caused the retracting cable to come off its runner and loop over one of the rollers. The cart's drive motor continued to operate, pulling the cable against the rewind drum and the resistance stripped the motor and sheared the gear teeth.

The trailing data cable was also pulled completely out of the cart control panel, necessitating its replacement. The system was temporarily rigged to allow all cars to be removed manually and was then inoperable until the repairs could be completed.

Final loss

Property Damage \$11,000.00



How can I find out more?

To find out more about Vero Engineering Insurance contact your broker or visit the Vero website www.vero.com.au.